Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Yazzie No. 102 AUM Site

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 142 Map ID: W70 **CERCLIS:** NNN000909070 Navajo Abandoned Mine Land Reclamation Program: NA-0154 Local name / Aliases: Yazzie #102 **Chapter and local area:** Cameron Chapter **County:** Coconino State: Arizona **Lat/Long:** 35.7952919774 N / -111.359860326 W **Nearby road and highway:** Highway 89 Local Post Office: Cameron, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** State Fee land **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. Claim and operator information: The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Chesser and Company in 1956, and H.F. Rogers in 1960. No

additional ownership / lease information was identified in the EPA/AUM database.

Number of residential structures within 200 feet of mine: None

Estimated volume of mine waste onsite: None

Part II Summary of radiological readings

Highest gamma radiation measurement:

39,060 counts per minute (cpm)

Describe any other radiological measurements:


A total of 1,465 gamma radiation measurements were collected from the mine site, ranging from 6,982 cpm to 39,060 cpm. The measurements collected in the pit/depression area were found at levels ranging from approximately 20,000 - 40,000 cpm. The measurements are represented in Figures 1 and 2.

Background Readings: 8,082 cpm; 7,021 cpm

Background Average: 7,552 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1465

 Minimum:
 6982,00000

 Maximum:
 39060,00000

 Sum:
 16351792,00000

 Mean:
 11161,63276

 Median:
 10261,00000

 Standard Deviation:
 3119,82847

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0154

NAMLRP Mine features: 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work and	ctatuc.
COUNCI VCU	i cciainauvii	wui K anu	Status.

Adits

None

Waste Piles

None

Pits

None

Shafts

None

Other Debris and Mine Features

Large depression in the center of the site

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: Windmill Well approximately 3.25 mi SW of the site; Little Colorado River Basin approximately 1.5 mi E of the site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Yazzie No. 102 mine consists of an area of 44,840.24 m². The mine was identified as being operational from 1956 to 1960. Historical documents showed the operator of the mine as Chesser and Company in 1956, and H.F. Rogers in 1960. While operational, the mine had a total reported production volume of 1,610 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1. Yazzie No. 102 mine site



Photo 2. Yazzie No. 102 mine site, depression area



Photo 3. Yazzie No. 102 mine site, depression area

Part VII Contacts Reports and Information

Name: <u>Stanley Edison (928) 871-6861</u>

Eugene Esplain (928) 871-7331

Title or official role (if any): Navajo EPA Superfund Program

Address: PO Box 2946, Window Rock, AZ 86515

Information provided: <u>Lead Regulatory Agency</u>

Name:	
Title or official role (if any):	
Address:	
Telephone number:	-
Information provided:	_
Name:	-
Title or official role (if any):	_
Telephone number:	-
Information provided:	
	-
Name:	_
Title or official role (if any):	_
Telephone number:	-
Information provided:	_





Figure 2 - Gamma Radiation Measurements Yazzie No. 102 (142) Cameron Chapter, Navajo Nation




Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000

Average background 7,552 cpm





Mine Site Boundary



Gamma survey conducted 11/2010 Measured as counts per minute (cpm)